DG Flugzeugbau GmbH 76646 Bruchsal	Technical note No. 1000/21	page 1 from 1
Subject	: Main wheel brake system	
Effectivity	Type: DG-1000, variants DG-1000S and DG-1000T only when equipped with a nose wheel.	
Accomplishment	: Mandatory latest March 31. 2012	
Reason	It was detected that with wear of the brake pads the brake calliper touches the landing gear strut. So only 1 of the 2 brake pads brakes, which results in reduced braking efficiency and increased wear of the brake pad.	
	To overcome this shortcoming the wheel must be shifted 3 r side to provide clearance between brake calliper and LG stru allowable wear of the brake pads.	
Instructions	1. Modify the mounting of the main wheel and brake callips instruction no. 1 for TN1000/21.	er according to working
	 Maintenance manual: DG-1000S and DG-1000T: Exchange the following mar pages issued July 2011 marked with TN1000/21: 0.2, 0.6 	
Material	 working instruction no. 1 for TN1000/21 1 ring 5FW4/3 1 bush 5FW4/1length 29.5 mm (or shorten existing bush yo 4 bolts M6x24 LN9037 5 selflocking nuts M6 DIN985-8 zn 1 selflocking nut M8 DIN985-8 zn 8 washers 6.4 DIN125 St zn suitable metal glue e.g. Uhu Plus schnellfest lock wire 	urself)
Weight and balance	: influence negligible	
Remarks	: Instructions No. 2 may be executed by the pilot/owner hims inspected and entered in the aircraft logs by a licensed inspecthe next annual inspection.	
	 Instructions No. 1: EASA countries: The actions have to be performed in a organisation, or in a Part M, Subpart F approved organi regulations of the Part M and released according to M.4 Non EASA countries: The actions have to be performed workshop. All instructions are to be inspected and enter by a licensed inspector. 	sation according to the A.801. I in a licensed
Bruchsal, date: 26.08.2011		
Author: W. Dirks	Modifications approved by EASA Date 21.09.2011 under Approval No. 10036593	

Wilhelm Do