Glaser-Dirks Flugzeugbau GmbH

Im Schollengarion 19-20, 7520 Bruchssl 4 Telefon 07257-1071 Telex 7822410 GLDG LBA anerkennter Herstellungsbotricb IB 25

Technical Note TN 826/18 Page 1 of 2

LBA anerkannter Luftfahrttechnischer Betrieb IIA 279

Subject: Engine extension/retraction drive.

Applicability: DG-400's works numbers 4-1 to 4-188.

Priority: Procedure 1, 2 must be executed immediately.

Procedure 3, 4 must be executed within 90 days.

Description: On one DG-400 damage has occurred to the drive

pinion gears on the spindle motor that operates the engine extension/retraction mechanism. This damage has been caused by a defective gas-strut with insufficient pressure which has resulted in increased loads on the spindle motor's pinion

gears.

Procedure 1: The maximum permitted time to extend the engine is 13 seconds. If this time is exceeded, then the

gas-strut is too weak and must be replaced.

The following pages of the aircraft hand books

must be replaced:

Flight Manual, page 29 (new version February

1987).

Maintenance Manual, page 33 (new version February

1987).

Maintenance Manual, diagram 7 (new version Februa-

ry 1987).

Procedure 2: Check the engine extension time.

Procedure 3: If the extension time exceeds 13 sec. the gasstrut needs to be replaced. It must be replaced

with one of type 10-02-250-600/1200 N, available

from Glaser-Dirks.

See page 41 of the Maintenance Manual for the

gas-strut replacement procedure.

Procedure 4: Modification of the spindle-drive.

The mounting plate between the spindle motor and the gearbox has to be replaced in order to reduce the amount of free-play between the drive gear and

the gearbox.

In order to complete the replacement work, please refer to the following service instruction 1/10/86.

Glaser-Dirks Flugzeugbau GmbH Im Schollengarten 19-20, 7520 Bruchsal 4 Telefon 07257-1071 Tolex 7822410 GLDG LBA anerkennter Herstellungsbetrieb IB 25 LBA anerkannter Luftfahrttechnischer Betrieb IIA 279

Technical Note TN 826/18

Page 2 of 2

Note:

Procedures 1 and 2 may be performed by the aircraft owner.

Procedures 3 and 4 must be performed and inspected

by a licensed repair shop.

The aircraft log must be updated to indicate to Procedures 1, 3 and 4 have been performed, reference made to Technical Note 826/18.

Author

Bruchsal 4 March 10th 87

William Oth Dipl.Ing. W. Dirks

Type certification inspector

U. Siliida.

LBA-Approved:

The German original of this TN has been approved by the LBA under the date of April 10th 1987 and is signed by Mr. Skov. The translation into English has been done using the boot available knowledge. the best available knowledge and judgement. In any case of doubt, the German original is to be considered authorative.

Service Instruction 1/10/86

Page 1 of 2


## <u>Instructions</u> for the modification of the spindle drive

## a) Removal\_of the <u>drive</u> motor

 Extend the engine fully. Cut and remove the rubber cord attached to the forward engine doors.

Remove the canopy, and in order to secure the engine, tie a rope of at least 4 mm in diameter between the centre of the propeller and the canopy hinge.

- 2. Remove the large brass gear wheel (4R12) by bending the tab-washer (A 30 DIN 70952 St) back carefully with a screwdriver and undo the slotted nut (M 30 x 1,5) with a crescent wrench (45/50).
- 3. Lift the gear wheel carefully using a rubber hammer.
- 4. Remove the two M 60 x 50 bolts that attach the drive motor mechanism and disconnect all of the wiring connected to the motor. The electrical connectors are located on the cover of the flap operating lever on the left hand side of the engine compartment, and in order to disconnect them the heat-shrink tubing must be cut off.
- b) Disassembly of the drive motor and replacement of the separator plate



1. Remove the three slotted-head bolts (M3) on the underside of the separator plate and then remove the gearbox.

Service Instruction 1/10/86

Page 2 of 2

Unscrew the four countersunk bolts (two are M3 and two are M4) in order to remove the old mounting plate from 2. spindle motor. The old mounting plate and the spacing ring can be discarded as they are no longer required.

Both the M3 slotted-head bolts and the M3 and M4 Note: countersunk bolts are secured with Loctite. If they should prove difficult to remove, use a soldering iron (of at least 100 watts) to heat the bolts up to degrees C (300 F).

- 3. Check the motor's exposed drive gears for signs damage (broken teeth, excessive wear etc.). If the gears are damaged, a replacement motor can be obtained from Glaser-Dirks.
- The new mounting plate is reassembled using three round 4. head bolts (M 3 x 10 DIN 964 Stzn) instead of the slotted-head bolts (M 3).

Note: All bolts on the gearbox are to be secured with Loctite 72 b (672). Use sparingly!

c) Reinstalling the gearbox and spindle motor

> Reassemble the gearbox and re-attach the spindle motor reversing the steps used to removed them. Leave away the washers below the M6 locknuts of the two M6 x 50 bolts. Reconnect the cables to the spindle motor (Connect No. 75 -751, No. 76 - No. 761) and insulate with heat-shrink tubing (as described below). The heat-shrink tubing must be heated with a heat-gun or a soldering iron in order shrink it tightly around the connectors.

1 x Mounting plate 4 R 11 2 x Locknuts M6 DIN 985.8 St zn Materials:

3 x Roundhead bolts M3 x 10 DIN 964 St zn

1 x piece 1/2" Heat-shrink tubing 1/2" type H. 8 cm long.

Special tools:

1 x Wrench for slotted nuts 45/50 for spindle-drive available from Glaser-Dirks

1 x Soldering iron (100 watts)

U. Sdidu

Bruchsal, 10th March 1987

Prepared by:

Approved by:

W. D.