Manual amendments

No.	Page	Description	Date	Signature
1	2, 3, 4, 34, 57, 63, 64,	Engine, powerplant drive belt	Oct. 1999	U
	93,	tension, DEI- circuit breaker,		
	drawing W57	manual revision		
		TN 843/13		
2	2, 3, 4, 11, 19, 27, 45,	Greasing schedule, new	Jan. 2001	
	47, 48, 49, 51, 62, 71,	attachment of the throttle		
	79, 91,	cable from ser.no 5E213 on,		
	wiring diagram 5E101,	manual revision		
	drawing W40	TN 843/16		
3	2, 3, 4, 5, 23 - 28, 30 -	Engine control, manual	March	
	34, 36a, 37, 49 - 51, 54,	extension and retraction	2002	
	72, 73, 78, 79, 84, 91,	control, carburettors, engine		
	93,	doors rubber cord, manual		
	wiring schemes 5E101	revision		
	issues G and H, 5E218	TN 843/17		
4	2, 4, 24, 91,	Extension-retraction unit,	June	
	diagram 13b, wiring	TN 843/18 issue 2	2003	
	scheme 5E101 issue I,			
	drawing 5E218			
5	2, 3, 4, 24, 25, 47, 48,	Manual revision	March	
	50, 64, 65, 68, 73, 75,	Powerplant: retaining cable	2004	
	76,	mounting in fuselage		
	diagram 18, drawing	TN 843/19		
	5M110			
6	2, 3, 4, 5, 42, 49, 68,	Manual revision TN 843/24	January	
	89, 89a, 93,		2006	
	Enclosure 1			

	Content	Page	LBA
0	A immedia and limitations	5	approved
0	Airworthiness limitations	5	Jan. 06
1	System description and adjustment data	6	Nov. 98
1. 1.1	System description and adjustment data	7	issued Nov. 98
1.1	Wing and tailplane setting data	8	INOV. 98
1.2	Elevator control and trim system	8 9	., .,
1.3	Rudder control	10	
1.3	Aileron and wing flaps control	10	Jan. 01
1.4	" "	11	Nov. 98
		12	""
1.5	Airbrake control and wheel brake	13	
1.6	Undercarriage	14	
1.0	" "	16	
1.7	Tow hooks	10	
1.8	Water ballast system	18	" "
1.9	Massbalance and weights of control surfaces	10	Jan. 01
1.10	Fore and aft play of the wings	20	Nov. 98
1.11	Power plant	20	" "
1.11		22	
		22	July 02
1.12	Retraction-extension mechanism	23	March 04
1.12	Fuel system	25	March 04
1.15		25	July 02
		20 27	July 02
		28	
	" "	20	Nov. 98
1.14	Electrical system	30	July 02
1.17		31	July 02
	" "	32	
		33	
		34	
		35	Nov. 98
		36	""
1.15	Canopy operating handles	36a	July 02
2.	Inspections		
2.1	Daily inspection	37	July 02
2.2	Regular inspections	37	""
2.2		38	Nov. 98
2.3	Inspection after a heavy landing	39	" "
2.0		40	., .,
	" "	41	
2.4	Inspection procedure for increase of service	42	Jan. 06
2	time	43	Nov. 98
	······	1.5	1101.20

	Content	Pa	ge issued
3.	Maintenance		
3.1	General maintenance	44	4 Nov. 98
3.2	Maintenance of the airframe	4	
3.3	Greasing programme	4	
3.4 3.5	Damage of the airframe	4	
3.5	Servicing the engine	4' 4'	
		4	
			Juli . 00
	"	50	
	" "	5	2
	" "	52	2 Nov. 98
4.	Detailed instructions for assen servicing work	nbly and	
4.1	Water ballast system	5.	ς ""
4.2	Replacement of control circuit c		
4.3	Adjustment and servicing of the		July 02
1.5	circuit	54	4 " "
4.4	Removal and installation of the	5.	5 Nov. 98
	undercarriage (main wheel)	5	6 " "
4.5	Filling and bleeding the hydraul	lic disc $5'$	7 Oct. 99
4.6	brake Steerable nose wheel	51	8 Nov. 98
4.0	Working instructions for heat-sl		
	tubing	unink 0	" "
4.8	Securing with Loctite	6	" "
4.9	Section not effective	(6	
4.10	Replacement of wing fuel tanks	6	
4.11	Mounting and tensioning of the	drive belt 65	
4 1 2			
4.12	Replacing the bearings of the up Belt pulley	oper drive 65	
4.13	Section not effective	(6)	7)
4.14	Replacement of the engine retai		⁸ Jan. 06
4.15	Filling and bleeding the cooling		9 Nov. 98
4.16	Installation and removal of the	powerplant 70	
	"	7	1 Jan. 01
	" "	72	2 July 02
	" "	7.	3 March 04
	" "	74	4 Nov. 98
	" "	7:	5 March 04
4.17	Removal and assembly of the en	ngine doors 70	6 March 04
4.18	Securing the propeller bolts	7	
4.19	Checking the ignition unit	73	8 July 02
	" "	7	
	" "	8	
4.20	Calibration of the fuel display in		
7.20		82 82	
1 01	Further DEL calibrations		
4.21	Further DEI calibrations	(ratraat unit 8	5
4.22	Installation and removal of the ext		• • • - j • • -
4.23	Reserved for further instruction: 2006 TN $843/24$	s (8) (C
Issued: Jal	nuary 2006 TN 843/24		3

	Content	Page	issued
5	Weight and balance	86	Nov. 98
	" "	87	" "
6.	Instrumentation and accessories list	88	
	" "	89	Jan. 06
	" "	89a	Jan. 06
7.	List of special tools	90	Nov. 98
8.	Partslist	91	June 03
	" "	92	Nov. 98
	" "	93	Jan. 06
Diagrams			issued
1	Elevator control, trim		April 90
2	Rudder control		
3	Aileron, wing flap and spoiler controls in the fuselag	je	
4	Aileron, wing flap and spoiler controls in the wings		
5	Tow releases		
6	Water ballast system		
7 8	Landing gear, hydraulic wheel brake		
8 9	Systems for static and total pressure Placards		Sept. 98
10	Steerable nose wheel		April 90
10	Powerplant		Sept. 98
12	Powerplant		
12 13b	Extension-retraction mechanism		June 03
14	Fuel system		Sept. 98
14a	Installation of the fuel filter		" "
15	Propellerbrake		
16	Engine door control		" "
17	Retaining cable		
18	Retaining cable		March 04
Enclosures			issued
Equipment li	st	(94)	Nov. 98
	checks and maintenance work	(95)	Nov. 98
5EP31 Instal	lation Dräger oxygen system		08.10.90
5EP50 Instal	lation ELT ACK		07.12.98
5E101 Wirin	g scheme issue I		25.06.03
5E102 Wiring plan DIN A 1 (in aircraft log) or			2.07.03
5E102 Wirin	g plan DIN A 1 together with		02.02.99
5E218 Amendment to the wiring plan 5E102			25.06.03
Instructions for inspection 500/20			July 1995
Questionnaire for TN 348/4			" "
Working instruction No. 1 for TN 348/4			Oct. 1994
Working instruction No. 2 for TN 348/4			1410.04
Tool for airbrake adjustment			14.10.94
Drawing W40 Drawing W51			30.11.99
Drawing W51 Drawing W57			20.11.96
Drawing W57 Drawing 8E210			10.09.99 22.05.97
Drawing 8E210 Drawing 5M110			22.03.97 23.10.02
•	Instructions for transponder Installation		Jan. 06
	instructions for transponder instantation		Juli. 00

Issued: January 2006 TN 843/24

Instructions for continued airworthiness

0 Airworthiness limitations

0.1 **Repairs:**

Repair or replace damaged parts prior to next flight. Follow the instructions of the DG-500MB repair manual. Repairs outside the scope of DG-500 MB repair manual and major repairs must be accomplished at a certified repair station or by a certified mechanic rated for composite aircraft structure work in accordance with DG repair methods. Use only genuine parts for all repairs.

0.2 Life time of the airframe

The maximum allowable operating time for composite sailplanes is 12000 flight hours. Therefore inspections according to sect. 2.4 of this manual have to be executed at 3000 h, 6000 h, 9000 h and every 1000 hours following thereafter.

0.3. Life time of components

- a) The following components of the power plant have to be replaced after 400 engine hours.
 - 1. All nuts and bolts on the engine
 - 2. The bearings of the upper drive belt pulley
- b) All flexible fuel lines and the gasket for the drainer valve have to be exchanged after 6 years.
- c) The **hoses of the cooling system** have to be exchanged after 6 years.
- d) The **drive belt** has to be exchanged after 50 engine hours.
- e) The 2 upper **rollers for the drive belt** have to be exchanged every 50 engine hours
- f) The **spark plugs** have to be exchanged after 25 engine hours.
- g) The **fabric straps of the safety harness** have to be exchanged after 12 years.
- h) The rubber cords in the elevator control system see sect. 1.2.6 and in the wing flap control system see sect. 1.4.6 have to be replaced at least every 6 years.

i) **Other components**

All other components like tow hook, wheels, gas struts, control system parts, bolts, pins etc. have no life time limitation, but should be replaced when worn, damaged or disqualified by excessive corrosion.

j) **Flexible fuel bags in the wings (option)** These have to be exchanged after 10 years.

2.4 Inspection procedure for increase of service time

1. General

The results of fatigue tests of wingspan sections have demonstrated that the service time of GFRP/CFRP gliders and motorgliders may be limited to 12000 hours, if for each individual glider (in addition to the obligatory annual inspections) the airworthiness is demonstrated according to a special multi-step inspection program particularly with regard to the service life.

2. Dates

When the glider has reached a service time of 3000 hours, an inspection must be done in accordance with the inspection program mentioned under point 3.

If the results of this inspection are positive or if any defects found have been duly repaired, the service time of the glider is extended by another 3000 hours to a total of 6000 hours (first step).

The above inspection program must be repeated when the glider has reached a service time of 6000 hours. If the results of this inspection are positive or if any defects found have been duly repaired, the service time of the glider is extended to 9000 hours (second step).

When the glider has reached a service time of 9000 h the above inspection program must be repeated. If the results of the inspection are still positive, or if any defects found have been duly repaired, the service time may be extended to a total of 10000 hours (third step).

Proceed analogous when reaching 10000 and 11000 hours (4. and 5. step).

With sticking piston rings the cylinders must be removed. Take out the piston rings and clean the grooves and the rings or replace the rings. Remove also any combustion deposits inside the pistons. **Caution:** Necessary repair work including removal of combustion deposits must be accomplished at a certified repair station rated for such engine work.

12a. Check the cylinder base for indications of leaking and/or damaged gaskets. When gaskets are damaged or leaking they must be exchanged. To accomplish this the engine has to be removed from the propeller mount.

Caution: The exchange of cylinder base gaskets must be accomplished at a certified repair station rated for such engine work.

13. Check the muffler for cracks and ensure mounting is secure. Check especially the cable which lifts the muffler during engine extension. Check the retaining cable for the muffler lifting cable incl. the rubber cord. Check the moving part at the front end of the muffler for any cracks. Check the exhaust manifold (already removed) for cracks. Reinstall the exhaust manifold, therefore remove any remains of the gaskets, install new gaskets. Check the function of the gas-spring at the muffler frame. Therefore retract the engine until the muffler pops downwards. The gasspring must press the muffler frame securely to its lower stop. Check the length of the cable which lifts the muffler. To accomplish this extend the engine and press the muffler body in downward direction at its front end with a force of approx. 5 daN (11 lbs.). If the cable is too long or if the spring in the cable has been permanently stretched, the muffler will interfere with the exhaust manifold.

Check the spring pressure at the coupling of exhaust manifold to muffler. To accomplish this, measure the distance between the brackets for the spring couplings at the muffler pipe and at the movable part of the muffler in disengaged and in operating position. Extend the powerplant to operating position via the ignition switch. As soon as the extension stops, lift the red cover of the manual extension switch and switch off the ignition. In operating position the distance should be approx. 1 mm (0.04 in.) smaller than when disengaged. If the difference should be less than 0.5 mm (0.02 in.) you have to adjust to 1mm using the nut on the eyebolt. By this procedure you will pull the muffler forwards in its frame. Note: With new manifold and/or new movable part the difference should be adjusted to 2 - 3 mm (0.04 - 0.12 in.) to allow breaking in of the parts.

14. Check all engine nuts and bolts with a torque wrench (see sect. 1.11.10).

4.14 **Replacement of the engine retaining cable**

Please refer to diagram 17 and diagram 18 with retaining cable shock absorber (standard from ser. no. 5E243B20 or retrofitted according to TN 843/19)

- 1. Extend the powerplant.
- 2. Remove the access panel from the rear engine bay floor.
- 3. Remove the engine retaining cable from the propeller mount. Let the cable retract slowly, otherwise the retraction bungee may jump from its pulley located inside the rear end of the fuselage. The bungee pulley is accessible via the access hole inside the tailwheel box.
- 4. Pull out the bungee via the access hole in the rear engine bay floor until you reach the terminal of the retaining cable.
- 5. Fix the bungee to the floor to prevent it from disappearing into the fuselage boom.
- 6. Cut off the retaining cable and pull it out. Don't damage the bungee! Don't loose the steel washer.
- 7. Attach the new cable with thimble and Nicopress sleeve to the bungee. Press the Nicopress sleeves. The end of the cable must be inside the second Nicopress sleeve. Fit the steel washer onto the cable und wrap the washer with the Nicopress sleeves twice with Tesaband 651.
- 8. Push the retaining cable via the adjustment screw through the rear engine bay bulkhead and pull it forwards. Don't forget to install the steel washer between Nicopress sleeve and bulkhead.
- 9. Let the bungee retract slowly into the aft fuselage
- 10. Install the retaining cable together with thimble and Nicopress sleeve to the propeller mount. Don't press the sleeve. Adjust the position of the powerplant according to section 1.12.4. Tighten the cable and press the Nicopress sleeve. Cut off the excess cable.
- 11. Check again the length of the retaining cable. See section 1.12.4. Adjustment is possible at the adjustment screw at the rear bulkhead.
- 12. Reinstall the access cover to the rear engine bay floor.

Material:

Steel cable diameter 3.2 mm (1/8 in.) type see sect. 4.2 approx. 2.3 m (91 in.) long

2 thimbles 3mm DIN 6899A

3 Nicopress sleeves 28-3-M

Tesaband 651 (self-adhesive textile tape)

Issued:January 2006 TN 843/24

6.5 VHF transceiver		
Manufacturer	Туре	Certification No.
Dittel	FSG-40 S	10.911/45
	FSG-50	10.911/71
	FSG-60 M	10.911/72
	FSG-70,71 M	10.911/81
	FSG-90	10.911/98JTSO
	FSG-2T	LBA.0.10.911/103JTSO
Becker	AR 3201-(1)	10.911/76
	AR 2008/25 (A)	10.911/48
	AR 4201	JTSO-2C37 D, ED-23A
Filser	ATR 720 A	10.911/74
	ATR 720 C	10.911/83
	ATR 500	O.10.911/106JTSO
	ATR 600	LBA.0.10.911/113JTSO

Note: Only radios with diameter $58mm (2 \frac{1}{4} in.)$ can be installed at the assigned place in the console below the instrument panel.

6.6	Variometer Manufacturer	Type	Certification No.
	Winter	5 St VM5 (dia.58 mm) <u>+</u> 5 m/sec Ident.No.5451 +1000 ft/min ident.No.5452	TS 10.230/14
	Winter	$\pm 10 \text{ kts Ident.No.5453}$ 5 StV5 (dia.80 mm)	TS 10.230/13
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<u>+5</u> m/sec Ident.No.5251 +1000 ft/min Ident.No.5252	10 10.200/10
		± 10 kts Ident.No.5253	
6.7 Turn and bank indicator			
	Manufacturer Apparatebau	Туре	Certification No.
	Gauting	WZ-402/31 12 V	10.241/8
6.8	Engine instrument	ation	
(RPM, fuel, CHT, voltmeter, engine elapsed - time indicator, EGT as an Option)			indicator, EGT as an
	Manufacturer	Туре	
	DG Flugzeugbau	DEI-MC 500 B	main instrument, front cockpit
		DEI-M 500 ZB	in the rear cockpit
Issu	ed: January 2006	TM 843/24	89

6.8 Instruments which are not part of the minimum equipment:

Transponders: Transponders certified for aircraft use according to TSO or JTSO or ETSO standards may be installed.

Other instruments and equipment (eg. variometers, gliding computers or flight data recorders):

Instruments and other equipment may be installed if they do not in themselves, or by their effect upon the sailplane, constitute a hazard to safe operation.

Caution: If additional instruments or equipment are to be installed after production of the glider, it must be assured that they will be installed in the places provided by the design. If installed in other places it must be assured that they are secured safely.

Electrical instruments and equipment must be connected via appropriately rated fuses, the power consumption of each single part should not exceed 3A.

After installation raise a new weight and balance report.

8.2 **Parts for the electrical system**

60510891	Battery 6V, 10 or 12Ah equipped with screw - terminals
40876070	DEI MC 500 B
40876090	rear panel DEI MC 500 ZB
40876030	Control unit 8E103 (including relays and regulator)
60510464	Limit-switch engine retracted and engine extended 164-574
Ser.no B1 -	-B15 with instruction 5 from TN 843/17 not executed:
60510476	Manual extension-retraction switch APR 20-647H
60510475	Switch to switch over from normal to emergency extension-
	retraction APR 20-646H
Ser.no B1 -	-B15 with instruction 5 from TN 843/17 executed, ser.no. B16
and on:	
60510482	Manual extension-retraction switch APEM 637 H/2
60510483	Switch to switch over from normal to emergency extension-
	retraction APEM 5636 MA
60510476	Manual extension-retraction switch APR 20-647H
60510475	Switch to switch over from normal to emergency extension-
	retraction APR 20-646H
60510813	Master switch Bosch 0341001001
60510812	Key for master switch Bosch 0341001001
60510478	Engine master switch 631 H-215A
60510370	Press-button SECME 07 17801 21 for starter
	and for test of second fuel pump
60510391	Circuit breaker Klixon 7277-2-15A for spindledrive
60510394	Circuit breaker Klixon 7277-2-5A for DEI
60510385	Circuit breaker ETA 2A
60510386	Circuit breaker ETA 3A
60510388	Circuit breaker ETA 10A
60510436	Fuse 535257 60 A for batteries
60510440	Fuse 250V 0.2A 5x20 m for fire warning light
60510419	Fuse 250V 2A 5x20 m for second fuel pump
60510550	Proximity switch Insor IPCT 1212
40576150	Proximity switch ready assembled with wiring and plug
60510796	Socket BSB 12 (in main bulkhead)
60510797	plug BSK12 for socket BSB 12

I