DG Flugzeugbau GmbH 76646 Bruchsal **Technical Note** No. 843/25

page 1 from 1

Subject : Power plant ignition system

Effectivity : DG-500 M all Ser. No.'s.

Accomplishment : In case of defect of one ignition box

Reason : 1. The Bosch Polarfire ignition boxes used until now with the Rotax 535 C

engine, are no longer available. In case of defect of one the electronic boxes the ignition system has to be modified according to working instruction No. 1. Both

electronic boxes have to be exchanged.

2. The Ducati ignition boxes used by Rotax (installed with TM843/4 or during serial-production) are no longer available. In case of defect of one box you have to install Ducati 432372501 boxes and change the wiring according to working instruction No. 2. Both electronic boxes have to be exchanged.

Instructions : 1. Remove front and rear DEI and ship to manufacturer for installation of filters, reinstall the modified DEI's.

2. If the engine is equipped with Bosch Polarfire ignition electronic boxes:

a. Modify the system according to working instruction No. 1 and No. 2 for TN

843/25.

Exchange the manual to "Manual for ROTAX-engine type 535 C, 2nd

edition January 1992".

b. File drawing 5E43 to the aircraft logs in addition to page 16 of the engine

manual.

3. If the engine is equipped with Ducati ignition electronic boxes

a. Modify the system according to working instruction no. 2

b. File drawing 5E43 to the aircraft logs in addition to page 16 of the engine

manual.

Material : Instruction 1:

a. working instructions no. 1 and 2 Service kit No. 21000118

b. Manual for ROTAX-engine type 535 C, 2nd edition January 1992

c. drawing 5E43

Instruction 2:

a. working instruction no. 2 Service kit No. 21000119

b. drawing 5E43

Weight and balance : influence negligible

Remarks : Instructions are to be executed by the manufacturer or by a licensed workshop and

to be inspected and entered in the aircraft logs by a licensed inspector.

Bruchsal


Date: March 22.2007

Author: . EASA approved on: 4th May 2007

Dipl. Ing. W. Dirks

Under approval No. EASA.A.C.06832

Wilhelm Da



Zusatz zu Seite 16 Motorhandbuch Rotax 535 amendment to page 16 of the Rotax 535 engine manual

	Toleranzen nach Arbeitsanweisung BA 1 Schweißen nach Arbeitsanweisung SA 1				Tag Gez. 14.07.06		Name Könen		DG Flugzeugbau GmbH
					Gepr. Norm.				76646 Bruchsal Otto-Lilienthal-Weg 2
	Kadama	Xag			Maßstab " " " Maße ohne Toleranz- ang. nach:	Änd El		er Verkabelung für Ducati Zündboxen 432372501 en of the wiring for Ducati ignition boxes 432372501	P 5E43
Ausg.	Änderung	ÄΜ	Tag	Name					

Modification of the engine ignition unit to Ducati 432372501 ignition electronic boxes

1. Remove ignition boxes with holder 5M65. Pull off the spark plug connectors and remove the spark plugs, install BR8ES spark plugs.

Note: The electronic boxes with ignition (high voltage) wires and spark plug connectors, part 5M65 and the spark plugs won't be used any more. Remove bushes 5M66 from part 5M65 for further use.

2. The spark plug connectors have to be exchanged for NGK TB 05 EMA. The ignition (high voltage) wires must have the following lengths. If necessary shorten the wires after removing the spark plug connectors.

spark plug	length of wire
1	490
2	460
3	550
4	445

- 3. Install ignition boxes according to drawing 5M73 with holder 5M72 and bushes 5M62.
- 4. Change the wiring loom according to working instruction no. 2.
- 5. Retract the engine carefully up to the electronic boxes. Check if there is enough space between the boxes and the structure, min. 2 mm (.08 in.).

 If there is not enough clearance, the seats of the outside box may be filed down as far as necessary. Make sure that the seats have a plane surface!
- 6. Check the ignition timing according to the maintenance manual sect. 4.12.1.
- 7. Accomplish a test run with magneto check

Necessary material

piece	description	
1	Service kit Art. No. 21000118	

Inhalt:

piece	description	Anzahl	Bezeichnung
2	Ducati 432372501 ignition	4	M 6 DIN 985-8 zn
	boxes		
2	ignition box filter 4E28	1	Ty-rap 3,6x360
4	spark plug connectors NGK TB	23	Ty-rap 4,8x186
	05 EMA		
4	spark plug BR8ES	12	male spade connector
			RSQ 7610 6,1-1
1	5M 72 with ultra bushes	12	female spade connector
	0118036		RSQ 7600 A 6,3-1
2	M 6 x 55 DIN 931-8.8 zn	700mm	heat shrink tubing 1/2" FT500
2	M 6 x 35 DIN 912-8 zn	600mm	heat shrink tubing 19-9,5
			FT5550
8	6,4 DIN 125 St zn	700mm	heat shrink tubing DERAY H
			1/4"

Enclosures: drawings 5M73, 5M74

Bruchsal, March, 22.2007

Modification of the powerplant – ignition unit to Ducati 432372501 ignition electronic boxes

A: Only in case the engine is equipped with Ducati 432372501 boxes: Remove the ignition electronic boxes, they will not be used again.

B: Modification of the wiring

- 1. Open the cable harness from the ignition boxes up to 360 mm measured from the engine block (see sketch 1). The wires coloured white, brown, black and red are for ignition box 1 and white/red, brown, black and red are for ignition box 2.
- 2. The wires leading to ignition box I must be shortened to 120 mm length and the wires to ignition box II to 130 mm length measured from the opening of the cable harness (see sketch 1).
- 3. Cut the white and the white/red wire by 40 mm. Slip pieces of heat shrink tubing over the shortened wires, crimp one spade connector (female) to each of the wires and shrink the tubing.
- 4. Plug an ignition box filter (pict. 1) to each of the two cable shoes. Slip heat shrink tubing over the connections and shrink the tubing. Take care of the correct mounting direction. (see pict.2).
- 5. Crimp a spade connector (male) on each of the wires remaining from point 2. Connect the wires according to pict.2 to the filters, so that you have the same wire colours as on the other side of the filter.
- 6. The cable harness for the ignition box aft (BOX I) has to be shortened to 480 mm (pic.2). The cable harness for the front ignition box (BOX II) has to be shortened to 490 mm (pic.2). Slip heat shrink tubing over the cable harness as indicated in picture 2 and shrink the tubing. Note: 20mm of the wires must not be covered by the heat shrink tubing see pict.2.
- 7. Crimp cable shoes to the wires according to pict.2
- 8. Connect the wires to the ignition boxes according to pict.2.
- 9. Slip heat shrink tubing over every connection.
- 10. Cover the cable harness completely with heat shrink tubing.
- 11. The cable harness has to be fixed. The cable harness should not be able to vibrate or rub. Fix the cable harness according to pictures 3, 4 and 5 and drawing 5M74. The ty-raps have to tightened by hand.

necessary material:


pieces	Description
1	Service kit No.21000119

consisting of

piece	description	piec	e description
2	Ducati 432372501 ignition boxes	12	female spade connector RSQ
			7600 A 6,3-1
2	ignition box filter 4E28	700	mm heat shrink tubing DERAY H
			1/4"
20	Ty-raps 3,6x140	700:	mm heat shrink tubing 1/2" FT500
12	male spade connector RSQ 7610	600	mm heat shrink tubing 19-9,5
	6,1-1		FT5550




Picture 1




—□)—


Picture 2

Warning: don't mix up the wire colours!






Picture 3



Picture 4



Picture 5

