DG Flugzeugbau GmbH	Technical note	page 1 from 1
76646 Bruchsal	No. 800/35, 843/29	

Subject : Extension-retraction unit, rear fork of spindle-drive

Effectivity : DG-800 variants DG-800B (with spindle-drive Stross) and DG-808C

DG-500M variant DG-500MB

Accomplishment : DG-800B and DG-500MB for repair

DG-808C up to ser. no. 8-402, ser. no. 8-404 up to 406 and 8-410 for repair DG-808C ser. no. 8-403 and ser. no. 8-407 up to 409 and from ser. no. 8-411 on

during production

Reason : To increase the fatigue life of the rear fork of the spindle drive a new fork was

designed which is milled from a steel block. This replaces the original welded fork With DG-808C ser. no. 8-408 up to 8-410 and from ser. no. 8-412 on the fork will

be screwed directly into the push tube of the spindle drive.

Instructions : 1. DG-800B and DG-500MB and DG-808C up to ser. no. 8-402, ser. no. 8-404 up

to 406 and 8-410:

The fork 8M233/1 (drawing issue h) may be installed instead of the welded fork without further modifications, but use only 1 washer between nut and fork at the M10 bolt, see drawing 8M227 issue i.

2. With DG-808C ser. no. 8-403 and ser. no. 8-407 up to 409 and from ser. no. 8-411 on another fork 8M333 will be used. This fork will be screwed directly into the push tube of the spindle drive according to drawing 8M327. The adapter 8M233/2 and the bolt M8x45 LN9037 are no longer necessary.

3. With ser. no. 8-403 and ser. no. 8-407 up to 409 and from ser. no. 8-411 on the

following maintenance manual pages will be exchanged:

0.1, 0.6, 8.1, diagram 10, issued April 2009

Material : DG-800B and DG-500MB for repair:

DG-808C up to ser. no. 8-402, ser. no. 8-404 up to 406 and 8-410 for repair:

rear fork of spindle-drive 8M233/1 (drawing issue h)

drawing 8M227 issue i

DG-808C ser. no. 8-403 and ser. no. 8-407 up to 409 and from ser. no. 8-411 on

spindle drive assembled with fork 8M333 according to drawing 8M327

manual pages see instruction 3

Weight and balance : influence negligible

Remarks : Instructions No. 1 may be executed by the pilot/owner himself and are to be

inspected and entered in the aircraft logs by a licensed inspector at latest with the

next annual inspection.

Bruchsal, date: April 17.2009

Wilhelm Da

Author: W. Dirks Modifications approved by EASA Date

under Approval No. EASA.A.C. 12168

