DG Flugzeugbau GmbH	Technical note	page 1 from 1
76646 Bruchsal	No. 7009 Revision 2	

Subject : Additional installation of an LS-latch (Röger-hook) to improve the emergency

canopy jettison

Effectivity : Type: LS-Sailplanes

Variant: LS7, all serial numbers

Accomplishment

: March 31. 2013 mandatory

Reason : Ad

: Additional installation of an LS-latch (similar to a Röger-hook) to improve the

emergency canopy jettison.

The variant LS7 is not equipped with a canopy emergency jettison LS hook as standard equipment. Tests made at LS and by Prof. Röger proved that there is a potential danger for the pilot in case of an emergency bail out if no hook is

installed.

These safety shortcomings will be resolved by executing this TN.

Instructions

1. Manual revisiones:

Flight Manual:

Exchange the following flight manual pages against new pages issued October 2010 marked with TN 7009, Rev. 1:

LS7: pages 0-1, 0-2, 3-1 and 4-4

Respect the changes marked in the right hand margin.

Maintenance Manual:

All changes with respect to the installation of the LS-latch are included in the revised Maintenance Manual, issued December 2009, see TN 7016.

2. Install the LS-latch according to the following documents:

- LS7: working instructions No. 1, for TN6025 and TN7009 and drawing BR-158 issue f.

3. TN 7011/2 has to be executed after installation of the LS-latch.

Material : 1. Flight manual pages see instruction no. 1.

2. Maintenance Manual LS7 issued December 2009.

- 3. Working instruction No. 1, for TN6025 and TN7009
- 4. Drawing BR-158 issue f
- 5. For a parts list, see drawing BR-158
- For a list of approved resins and other consumables, see applicable maintenance manual
- 7. TN 7011/2 incl. drawings 3R7-73a and 4R7-74

Weight and balance

: Influence negligible

Remarks

- 1. EASA countries: The actions have to be performed in a Part -145 approved organisation, or in a Part M, Subpart F approved organisation according to the regulations of the Part M and released according to M.A.801.
- 2. Non EASA countries: The actions have to be performed in a licensed workshop. All instructions are to be inspected and entered in the aircraft logs by a licensed inspector.
- 3. Not applicable to LS7-WL, as the LS-latch (Röger-hook) is standard equipment.
- 4. As the initial maintenance manuals will no longer be updated it is mandatory to use the maintenance manual see instruction 1 to maintain the glider after this TN has been performed.

Bruchsal, date:

Revision 2 27.06.2011,

2010

Author: W. Dirks

Modifications approved by EASA Date 28.09.2011 under Approval No. 10036674.

Willelm Do