0 General

0.1 Amendments

No.	Page	Description	Date
0.1	all	Combination of the initial Maintenance Manuals of the Variants DG-600M and DG- 600/18M, new standardized format	December 2009
0.2	0.11, 1.2, 1.4, 1.11, 1.12, 1.14, 1.18, 1.22, 1.24, 2.1, 2.3, 2.5, 3.1-3.3, 3.7, 4.2 4.7, 5.1, 6.2 - 6.4; 8.1-8.3, diagram 1	Miscellaneous changes to the contents of the latest amendments of the initial maintenance manuals	December 2009
1	0.1, 0.3 – 0.6, 0.11, 3.4, 3.7, 8.2, diagram 11	Fuel hoses TN DG-SS-02	October 2016
2	0.1, 0.3 – 0.6, 0.10, 1.1, 1.3 - 1.6, 4.6, 8.1 – 8.3 diagrams 3, 7b, 6F39	Manual revision TN DG-SS-07	August 2021
3	0.1, 0.3, 1.2 - 1.4	TN DG-SS-09 adjustment of elevator free play	December 2023

Maintenance Manual DG-600M

0 0.0 December 09 See manual amendments 0.1 " " 0.2 " " 0.3 " " 0.4 " " 0.5 " " 0.6 " " 0.7 " 0.6 0.7 " 0.8 0.9 " 0.10 0.10 " August 2021 0.11 " October 2016 0.12 " " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 December 1.6 " August 2021 December	3
0.1 " " 0.2 " " 0.3 " " 0.4 " " 0.5 " " 0.6 " " 0.7 " 0.8 0.9 " 0.10 " 0.10 " August 2021 0.11 " October 2016 0.12 " " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 December	
0.2 0.3 " " " 0.4 " " 0.5 " " " 0.6 " " " 0.7 " 0.8 " 0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021	
0.3 0.4 " " 0.5 " " 0.6 " " 0.7 " 0.8 " 0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	
0.4 0.5 " " 0.6 " " 0.7 " 0.8 " 0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	
0.3 0.6 " " 0.7 " 0.8 " 0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	
0.0 0.7 " 0.8 " 0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	
0.7 0.8 " 0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	
0.9 " 0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 1.2 " December 23 1.3 " August 2021 1.4 " August 2021 1.5 " August 2021 1.6 " August 2021	
0.10 " August 2021 0.11 " October 2016 0.12 " 1 1.1 December 09 1.2 " December 23 1.3 " August 2021 1.4 " August 2021 1.5 " August 2021 1.6 " August 2021	
0.11 " October 2016 0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 23 1.4 " August 2021 December 24 1.5 " August 2021 December 24 1.6 " August 2021 December 24	
0.12 " 1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 December 1.6 " August 2021 December	
1 1.1 December 09 August 2021 1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 December 1.6 " August 2021 December	
1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 December 1.6 " August 2021 December	
1.2 " December 23 1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 December 1.6 " August 2021 December	
1.3 " August 2021 December 1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	
1.4 " August 2021 December 1.5 " August 2021 1.6 " August 2021	er 23
1.5"August 20211.6"August 2021	
1.6 " August 2021	
-	
1.7 "	
1.8 "	
1.9 "	
1.10 "	
1.11 "	
1.12 "	
1.13 "	
1.14 "	
1.15 "	
1.16 "	
1.17 "	
1.18 "	
1.19 "	
1.20 "	
1.21 "	
1.22 "	
1.23 "	
1.24 "	
1.25 "	
1.26	
1.27	

0.2 List of effective pages

Maintenance Manual DG-600M

1.2 Elevator control and trim system

1.2.1 Control system

see diagram 1


1.2.2

ser. no.'s	all except 6-82M28		6-82M28 (with HT DG-800)	
	mm	in	mm	in
Up	61.5 <u>+</u> 1	2.42 <u>+</u> 0.04	46 <u>+</u> 2	1.81 <u>+</u> 0.08
Down	55 <u>+</u> 1	2.17 <u>+</u> 0.04	46 <u>+</u> 2	1.81 <u>+</u> 0.08
measured behind hinge	160	6.3	134	5.3
axis at				

Measurement:

Hold a measuring stick with one end on the floor. Deflect the elevator to neutral position by bringing the mark at the sealing in line with the upper end of the fin. Mark the 0-point on the stick. Then mark the up and down displacement.

measuring stick one end on the floor



1.2.3 Elevator stops

The elevator stops are located at the base of the control column and can be adjusted with a 10 mm open ended spanner.

1.2.4 Elevator control circuit free play

With the elevator held fixed in the zero position, the free play at the top of the control column can be ± 1.5 mm (± 0.06 in.).

Free play within the automatic elevator connection

Within the automatic elevator connection there should be no free play noticeable in the zero position when the elevator is moved at its trailing edge.

Any free play can be reduced by screwing in the adjustment screw on the automatic connector funnel.

Warning: In case the adjustment screw was turned in too far, the roller will jam inside the funnel and can't be moved or only with larger force to the front of the funnel. Moving the horizontal tailplane backwards for rigging might not be possible or only with large effort. Each time a bending force will act on the rod end which might lead to failure of the rod end with time.


For this reason after adjusting the free play it is necessary to check if the roller can be moved without force in the funnel

To accomplish this, remove the compete rod end with the roller or remove the roller from the rod end and stick it on an 8 mm f7 pin and move the roller in the funnel. Prior to removal of the rod end mark it's position.

If the roller can't be moved without force completely zo the front you must turn back the adjustment screw and bend back the sheet metal which was bent by the adjustment screw. Then adjust the free play again.

In case the roller has too much free play on the rod 6St50/2.


In case the glider was operated for a longer time with the adjustment screw turned in too far the rod end must be replaced by a new one 6St50/1.



After completion of this work check the elevator displacements and adjust if necessary.

1.2.5 Trim

The automatic trim mechanism should be adjusted so that with full forward (nose down) trim the control column is in the maximum forward position. The tensioning of the trim mechanism springs is adjusted as shown on the sketch.




The bungee interconnection between wing flap lever 6 St 9 and trim lever 2 St 32 is to be replaced, when worn or when elongated.

The length in unstretched condition y must be

110 mm (4.3 in.). The interconnection consists of 2 mm diam. bungee layer around 3 times.

1.2.6 Repair of the automatic trim mechanism bowden cable

In the event of a replacement bowden cable being installed, it should be cautioned that the cable must pass between the two parallel arms of the control column mechanism as shown in the sketch.



Warning: If the cable passes outside the mechanism column movement can be blocked.

1.2.7 Sealing the elevator

The elevator is sealed with a Teflon coated glass fibre fabric loop, see section 4.6a. Partlist see section 8.

1.3 Rudder control

1.3.1 Rudder control circuit

see diagram 2 DG-600M und DG-600/18M, resp. diagram 2a DG-600 and DG-600/18

1.3.2 Rudder deflections and tolerances


165-5 mm (\pm 30°) (6.5 - .2 inch) measured at 318 mm (12.52 inch) from the hinge axis.

1.3.3 Rudder stops

The rudder stops are located at the lower hinge pedestal and can be adjusted with an allen key wrench.

1.3.4 Axial free Play

The maximum allowable free play at the upper hinge point is 0.5 mm (0.02 inch)



1.3.5 Sealing the rudder

The rudder is sealed on both sides with a V sealing tape (3 M Scotch Flexodicht Band 2743 white) which is attached at the fin trailing edge. This seal is not to be removed. If damaged it should be replaced and sprayed with Teflon spray. Partlist see section 8.