0 General

0.1 Manual amendments

No.	Page	Description	Date
0.1	all	Combination of the initial	December 2009
		Maintenance Manuals of the	
		Variants DG-500/22 ELAN,	
		DG-500 ELAN Trainer, DG-	
		500/20 ELAN and DG-500	
		ELAN Orion, new	
		standardized format	
0.2	0,8, 1.9, 1.14, 4.2,	Miscellaneous changes to the	December 2009
	5.1, 6.1, 6.2	contents of the latest	
		amendments of the initial	
		maintenance manuals	
1	0.3, 0.4, 0.7, add	Wheel brake	July 2011
	diagram 7a	TN500/03	
2	0.3, 0.4, 0.7, 1.11,	Headrest securing ropes in the	September 2011
	2.1, 2.3, 2.4, 4.5, 4.6,	rear cockpit, manual	
	file working	amendments	
	instruction No. 1 for	TN500/05	
	TN348/20 issue 3 at		
	the end of the MM		
3	0.1, 0.3, 0.4, 1.4,	TN500/13	July 2019
	1.12, 1,16, 2.1 – 2.4,	Canopy lock, rear locking	
	6.3, diagrams 9 and	rods, manual revision	
	9b		
4	0.1, 0.3, 1.2, 1.3	TN500/17	December 2023
		adjustment of elevator free	
		play	

Maintenance Manual DG-500

Section	page	issued	replaced /	replaced /	replaced /	
)	0.0	December 09	*	*	•	
	0.1	See manual amendments				
	0.2	See manual an	nendments			
	0.3	See manual an	nendments			
	0.4	See manual an				
	0.5	December 09				
	0.6	"				
	0.7	"	July 11	September 11		
	0.8	"	5	1		
1	1.1	December 09				
	1.2	"	December 23			
	1.3	"	December 23			
	1.4	"	July 19			
	1.5	"	2			
	1.6	"				
	1.7	"				
	1.8	"				
	1.9	"				
	1.10.	"				
	1.11.	"	September 11			
	1.12.	"	July 19			
	1.13.	"				
	1.14.	"				
	1.15.	"				
	1.16.	"	July 19			
	1.17.	"				
2	2.1	December 09	September 11	July 19		
	2.2	"	July 19			
	2.3	"	September 11	July 19		
	2.4	"	September 11	July 19		
	2.5	"				
3	3.1	December 09				
	3.2	"				
	3.3	"				
	3.4	"				
4	4.1	December 09				
	4.2	"				
	4.3	"				
	4.4	"				
	4.5	"	September 11			
	4.6	"	September 11			
	4.7	"				

1.2 Elevator control and trim system

1.2.1 Control system see diagram 1

1.2.2 Elevator deflections and tolerances

Up 25.5° - 26°

Down $23.5^\circ - 24^\circ$

measured at 227 mm (8.94 in.) from hinge axis.


Measurement:

Hold a measuring stick with one end on the floor.

Set the elevator to zero by using a pattern. A drawing for the zero-pattern is available from DG Flugzeugbau.

Mark the 0-point on the stick.

Then measure the up and down deflections.



measuring stick one end on the floor

1.2.3 Elevator stops

The elevator stops are located at the rear control column and can be adjusted with a 10 mm open end wrench.

1.2.4 Elevator control circuit free play

With the elevator held fixed in the zero position, the free play at the top of the control column can be $\pm 2 \text{ mm} (\pm 0.08 \text{ in.})$.

Free play within the automatic elevator connection

Within the automatic elevator connection there should be no free play noticeable in the zero position when the elevator is moved at its trailing edge.

Any free play can be reduced by screwing in the adjustment screw on the automatic connector funnel.

Warning: In case the adjustment screw was turned in too far, the roller will jam inside the funnel and can't be moved or only with larger force to the front of the funnel. Moving the horizontal tailplane backwards for rigging might not be possible or only with large effort. Each time a bending force will act on the rod end which might lead to failure of the rod end with time.


For this reason after adjusting the free play it is necessary to check if the roller can be moved without force in the funnel.

To accomplish this, remove the compete rod end with the roller or remove the roller from the rod end and stick it on an 8 mm f7 pin and move the roller in the funnel. Prior to removal of the rod end mark it's position.

If the roller can't be moved without force completely zo the front you must turn back the adjustment screw and bend back the sheet metal which was bent by the adjustment screw. Then adjust the free play again.

In case the roller has too much free play on the rod end or if the roller is no more round you must replace the roller by a new one 5St95/3.

In case the glider was operated for a longer time with the adjustment screw turned in too far the rod end must be replaced by a new one 5St94.




After completion of this work check the elevator displacements and adjust if necessary.

1.2.5 Trim

The trim mechanism should be adjusted so that with full forward (nose down) trim the control column is in the maximum forward position. The tensioning of the trim mechanism springs is adjusted as shown in the

sketch. x = 340 mm (13.4 in.)The springs are located in the rear cockpit on the left hand side.



1.2.6 Pilot force reducing rubbercord

The rubber cord produces an elevator stick force in push direction. If the trim efficiency of your DG-500 in push direction is reduced, you have to inspect the rubber cord.

The rubber cord is located on the left hand side behind the main bulkhead below the baggage compartment floor.

The rubber cord runs from bellcrank 5St19 to a fork at the main bulkhead. The length of the rubber cord when loose should be 500 mm (19.7 in.).

If the cord is longer or worn it must be replaced.

The cord must be replaced at least every 6 years.