DG Flugzeugbau GmbH 76646 Bruchsal

**Technical Note** 

No. 1000/15

Subject : Throttle handle in rear Cockpit

Effectivity : DG-1000T, all ser. no.'s

Accomplishment : non, optional

: The DG-1000T may be equipped with a throttle handle in rear Cockpit Reason

> The interconnection between front and rear throttle handles is by means of 2 hydraulic cylinders and hydraulic lines. No friction brake will be installed, as the

page 1 from 1

system has enough internal resistance.

.Installation of the system by the manufacturer. External retrofit is not intended. Instructions : 1.

.Replace flight manual pages against new pages issued March 2008 marked

with TN1000/15.

Replace maintenance manual pages: 0.1, 0.3, 0.4, 0.6, 0.10, 1.19, 2.1 against new pages issued March 2008 marked with TN1000/15. Add diagram 19 and

enclosure 3.

Material : Manual pages see instruction 1

Weight and balance : Execute weight and balance after installation.

Remarks The instructions may be executed only by the manufacturer.

All instructions are to be inspected and entered in the aircraft logs by a licensed

inspector.

Bruchsal, date: March 3. 2008

Author:

Dipl. Ing. Wilhelm Dirks EASA approved on 17. April 2008

under Approval No. EASA.A.C.08935

Willelm Da