

LTA-Nr. 93-177

Subject: Flexible wing fuel tanks.

Effectivity: All DG-400 serial No. 4-3 to 4-46 is they are equipped with wing fuel tanks.

Accomplishment: Instruction 1 immediately.
Instruction 2 within 6 months.

Reason. On one DG-400 a wing fuel tank became leaking. So there might be the possibility that this will occur on other DG-400 too.

Instructions:

1. The wing fuel tanks are not to be used. Use only the fuselage tank.
2. Take out the wing fuel tanks following the instructions of the service manual page 45 section 4.8.
Send them to Glaser-Dirks for inspection and modification.
Assemble the modified tanks following the above mentioned instructions.
Instruction 1 of this technical note is raised then.

Remarks: The execution of instruction 1 and 2 can be done by the owner himself.

7520 Bruchsal 4, 15.09.1983

Wilhelm DA