

Subject : EASA approval of DG Service Infos

Effectivity : see list below

Accomplishment : see list below

Reason : Some of the service infos published on the DG web-site will be EASA approved with this technical note

Instructions : The Service Infos with the EASA approval will be published again on the DG web-site.

Material : Service Infos see list below

Bruchsal, date: 28.03.2008

Author: Modifications approved by EASA Date 23. April 2008
Dipl. Ing. Wilhelm Dirks under Approval No. EASA.A.C.09568

Wilhelm Dirks

Service Info No.	Subject	Effectivity	Accomplishment	initial issue
52	Gluing Plexiglas canopies	All	during repair	01.10.03
58	Powerplant / tension gas strut	DG-800B	during repair	3.02.06
59	Landing gear warning	DG-1000 up to 10-73	31.07.2006	17.05.06
60	Landing gear lock	DG-1000 up to 10-79	Instructions 1: 31.July.2006 Instructions 2: if necessary	17.05.06
61	Motor with gear and brake for spindle drive	DG-400, DG-800A	during repair	9.11.06
62	Landing gear lock	DG-1000S and T up to 10-90	On customer request	29.09.07
63	Starter motor for Rotax 505 engine	DG-400, DG-800A	during repair	28.03.07
67	Ballast box in the fin, foam rubber rings	DG-1000S and T	prior to next flight and upon changing the trim ballast in the ballast box	05.11.07
68	New material designations	all	during repair	28.03.08