

Gegenstand: Befestigung der Schultergurte
Betroffen: Segelflugzeug LS4, Änderung in der Serie
Dringlichkeit: entfällt
Vorgang: Der bisher benutzte Dreiecksbügel (Kennzeichnung FB 19) wird durch einen Bügel entsprechend Zeichnung 4R11-20 ersetzt
Maßnahmen: Ergänzung in Bauzeichnung 1BR-30
~~Lufttüchtigkeitsforderung LFSM 3653 erfüllt, siehe Anhang~~
Material: Siehe o.a. Zeichnung
Gewicht und SP-Lage: Bei Stückprüfung berücksichtigt
Hinweis: Änderung in der Serie
Anhang: Einzelnachweis EN-20 (LFSM 3653) vom 4.1.83
Umfassender Nachweis Versuche V5-2 vom 4.1.83
Zeichnung Schultergurtbügel 4R11-20 vom 5.1.83

Anerkannt vom
Luftfahrt-Bundesamt



J. Meiß
19. Jan. 1983

Subject: Shoulder strap attachment
Effectivity: Sailplane model LS4, modification during production
Accomplishment: not applicable
Reason: Triangular attachment bracket (marked FB 19) replaced by bracket according to drawing 4R11-20
Instructions: Addition to assembly drawing 1BR-30
Airworthiness requirement LFSM 3653 (corresponds to JAR 22.625(d)) fulfilled
Material: See mentioned drawing
Weight and Balance: Automatically taken into account during final production inspection
Remarks: Modification during production
Appendix: Single proof EN-20 (LFSM 3653) dated 4.1.83
Extensive proof Tests V5-2 dated 4.1.83
Drawing shoulder strap attachment bracket 4R11-20 dated 4.1.83