Glaser-Dirks Flugzeugbau GmbH Poutoch 4120, PLZ 0-76625 Tal. 972577/19-0, Fax 89/22 In: Schollengarion 19-20 D-75646 Bruchsal-Untergrombach LBA anerteinnter Herateilungsbetrieb IB 25 LEA anerkaanter Luftfahrttechnischer Geineb #A 278

Technical note

No. 301/17, 323/8, 359/18, No. 826/31, 348/7, 370/5, No. 866/4, 384/3, 873/7

SUBJECT

: Seat Harness

EFFECTIVITY

: DG-gliders and motorgliders

on request

ACCOMPLISHMENT

: with installation of new harness

REASON

: Some newer types of harnesses are not listet in the maintenance manuals of

all DG-types.

INSTRUCTIONS

: 1. The following newer types are acceptable for installation: Certification No.

Gadringer BAGU 5202 G " SCHUGU 2700 G 40.070/32 40.071/05 rubber coated adjuster bars

Autoflug BAGU FAG-12 D-0 40.070/47 SCHUGU FAG-12 H-0 40.071/25

Schroth 4-01-0 104

40.073/11

Page 1 from 1

Install the new harness similar to the existing harness.

- 2. If you install one of these types, file this TN as enclosure into your aircraft maintenance manual.
- 3. Enter the new harness in the equipment list of your aircraft or write a new equipment list.

REMARKS

: The instructions may be executed by the owner.

They are to be inspected and entered in the aircraft logs by a licensed inspector.

Bruchsal 4, date Jan. 24, 1996

Author: W. Dirks

W. Our

LBA - approved:

The German original of this TN has been approved by the LBA under the date of 4. Mar. 1996 and is signed by Mr. Fendt. The translation into English has been done by best knowledge and judgement.

Type certification inspector:

A. lange