



# Landing gear positive locking device

diagram17  
issued February 2008  
TN1000/13



installation of the notch (LG extended) to 10FW12/2



Installation of the locking catch. View LG retracted, locking catch not engaged