



Subject : Manual revisions

Effectivity type: DG- Single seaters
variants: DG-200 all

Accomplishment : December 31. 2020

Reason : If new flight manuals have been obtained from DG it might be that some pages describing older versions of the canopy locking mechanism and jettison procedure are missing. These pages are now updated to contain the the information for all versions
Revision of flight and maintenance manual

Instructions : Manual revision: Exchange the following manual pages against new pages issued Septembert 2020 marked with TN DG-SS-06. Respect the marked changes.
DG-200: FM: 1a, 12, 16
DG-200/17FM: 17/1 (not changed, but may be missing), 17/1a, 17/12, 17/16
DG-200/17C FM: 17C1 (not changed, but may be missing), 17C 1a, 17C12, 17/16
Maintenance manual DG-200: 0.1, 0.3, 1.4, 1.23

Material : Manual pages see above

Weight and balance : No influence

Remarks : All instructions may be executed by the pilot/owner himself.
The actions are to be inspected and released by the pilot/owner (according to MA. 801 (b) 3. for EASA registered aircraft).
If you have any questions concerning this TN please contact DG
Flugzeugbau: Tel.: 0049 7251 3020-0, e-mail: dg@dg-flugzeugbau.de

Bruchsal, date:
23. September 2020

Author: Modifications/repairs approved under the authority of DOA Ref.
Wilhelm Dirks EASA.21J.530 under Minor Change No. TN DG-SS-05, dated 23.09.2020.

Wilhelm Dirks