Rolladen Schneider Technische Mitteilung Nr. 3009

Blatt 1

Ausgabe Edition 31.8.78

Gegenstand:

Haubenverriegelung

Betroffen:

Segelflugzeug LS3-a

Dringlichkeit:

Serienmäßig ab 1.9.1978.

davor wahlweise

Vorgang:

Die bisher benutzte Verriegelung erhält zusätzlich einen

Verriegelungspunkt beidseitig in Haubenmitte.

Maßnahmen und

Material:

Siehe Zeichnung 3BR-4

Gewicht und

SP-Lagen:

Immer im Wägebericht berücksichtigt.

Hinweise:

Einbau oder Umrüstung nur beim Hersteller.

Die Forderungen der LFSM bezüglich Notausstieg (4601 bis 4607)

werden in gleicher Weise wie bei der LS3-a erfüllt. Siehe

auch LS3-a GB-4-14 vom 1.3.78.

Subject:

Canopy Locking Mechanism

Effectivity:

Sailplane LS3-a

Accomplishment:

Standard equipment after 1.9.78, optional for earlier deliveries.

Reason:

An additional lock on both sides of the cockpit in the middle

of the canopy is being fitted.

Instructions and Materials:

See Drawing 3BR-4

Weight and

Balance:

Automatically included in weight and balance report.

Remarks:

Fitting or modification at the manufacturer only.

Regulations regarding emergency exit (LFSM 4601-4607) are

met as for LS3-a.

Anerkannt durch

. 8. ১ep. 1978

Bearbeitet: 4. 9. 78 Keek Geprift: 4. 5.78 Klaupha

Rolladen Schneider Flugzeugbau GmbH Technische Mitteilung Nr. 3009 Blatt 1

Ausgabe Edition 31.8.78

Gegenstand:

Haubenverriegelung

Betroffen:

Segelflugzeug LS3-a

Dringlichkeit:

entfällt

Vorgang:

Die bisher benutzte Verriegelung erhält zusätzlich einen

Verriegelungspunkt beidseitig in Haubenmitte.

Maßnahmen und

Material:

Siehe Zeichnung 3BR-4

Gewicht und

SP-Lagen:

Immer im Wägebericht berücksichtigt.

Hinweise:

Einbau oder Umrüstung nur beim Hersteller.

Die Forderungen der LFSM bezüglich Notausstieg (4601 bis 4607)

werden in gleicher Weise wie bei der LS3-a erfüllt. Siehe

auch LS3-a GB-4-14 vom 1.3.78.

Subject:

Canopy Locking Mechanism

Effectivity:

Sailplane LS3-a

Accomplishment:

Reason:

An additional lock on both sides of the cockpit in the middle

of the canopy is being fitted.

Instructions

and Materials:

See Drawing 3BR-4

Weight and

Balance:

Automatically included in weight and balance report.

Remarks:


Fitting or modification at the manufacturer only.

Regulations regarding emergency exit (LFSM 4601-4607) are


met as for LS3-a.

Bearbeitet: 4. 9. 78 Recek Geprüft: 4.9.78 klapha

Position am Haubenrahmen wird durch Schablone festgelegt



| 19 | 1 | 6 kt Schraube M6 × 22 | LN9037 | | 510 - 063 | |
|----|---|--|---------|--------------|-----------|--|
| 18 | 1 | U-Scheibe 8,3 × 17 | DIN 125 | | 640 -059 | |
| 17 | 1 | Nadellager (Klein) RHNA 061009 | | | | |
| 16 | 1 | U-Scheibe 6,3 × 12 | DIN 125 | | 640-055 | |
| 15 | 1 | Stoppmutter M6 | W9348 | | 610-004 | |
| 14 | 1 | Stoppmutter M6 | LN9348 | | 610 - 004 | |
| 13 | 1 | U-Scheibe 6,3×12 | DIN 125 | | 640-055 | |
| 12 | 1 | Buchse \$8 x 1 x 5,6 cadm. + Chrow. | DIN2391 | St35BK | | |
| 11 | 1 | 6kt Stoppmutter M4 | LN9348 | | 610 - 002 | |
| 10 | 1 | U-Scheibe 4,1 x 12 x 1 | DIN9021 | | 640 - 048 | |
| 9 | 1 | 6kt Schraube M4 × 18 | DIN 933 | | 500-229 | |
| 8 | 7 | Blechtreibschraube 3,9 × 16 | DW 7973 | | 500 -380 | |
| 7 | 1 | Rundkoptschraube M4 - 38 aut 18 gekurt | DIN 84 | 8 . 8 | 500 -560 | |



| | 6 | 1 | Stoppmutter M4 Griff | | | | | | LN9348 | | 610-002 | |
|---|----------|-------|--|----------------|----------|--|---------|------------|-------------|-----------|-------------|-----------|
| | 5 | 1 | | | | | | | | | | 4R8 |
| | 4 | 1 | Verriegelungsstange 1 * links/1 * rechts | | | | | | | | | 4R8 |
| | 3 | 1 | Haube | nver | iege | lunc | shebe | l li.u.re. | | | | 488 |
| | 2 | 7 | Haubenverriegelungsblech liu.re | | | | | | | | | 4RE |
| 寸 | 1 | 1 | Verried | gelun | gsh | ebe | chalte | rung | | | | 4R8 |
| 一 | Pos. | Stuck | | | | | | | LN, DIN | Werkstoff | Sact: - Nr. | Zeich |
| T | | | | | | | | | Mai1stat. | 1:1 | | |
| | | | | | | | | | | | . 2 | |
| - | | | | | | | Datum | Name | | | | |
| | <u>†</u> | | | · • • · · · | .+ | neart. | | | Ha | uhenvei | riegelui | $n\alpha$ |
| | | | | | <u> </u> | Gepr | 14.6.78 | Luke |] / / 🗸 | | | 19 |
| 1 | | | | | | Norm | | PAT | + | L53 | $\cdot a$ | |
| | | | | <u> </u> | <u>.</u> | Gez. | 8.6.78 | KHAluan | 4 | | | |
| | | | | | | Rolladen - Schneider Segelflugzeugbau | | | | 38R - | 4 | |
| 1 | Zust | | nderuna | Datum | Name | | | | | | | |