

Gegenstand: Schultergurtaufhängung
Betroffen: LS-Segelflugzeuge LS4 und LS4-a
Dringlichkeit: Änderung in Serie
Vorgang: Bisher benutzte Befestigungen werden durch Teil Nr. 4R11-21 ersetzt, dann muß der Fahrwerkskasten der Zeichnung 1GR-5a entsprechen
Maßnahmen: Ergänzung in Bauzeichnung 1BR-30
Material: Siehe o.a. Zeichnungen
Gewicht und SP-Lage: Bei Stückprüfung berücksichtigt
Hinweis: Änderung in Serie, Versuche und Nachweise zu TM 4011 decken diese Änderung ab
Anhang: Zeichnungen 4R11-21, 1GR-5a, 1BR-30
Anerkannt:



grüß
22. Nov. 1984

Subject: Shoulder strap attachment bracket
Effectivity: Sailplane models LS4 and LS4-a
Accomplishment: Modification during production
Reason: Attachment brackets at landing gear box No.1GR-5a are replaced by part No. 4R11-21
Instructions: Addition to assembly drawing 1BR-30
Materials: See mentioned drawings
Weight and Balance: Taken into account during final production inspection
Remarks: Modification during production. Tests and proof for TB 4011 cover this modification
Appendix: Drawings 4R11-21, 1GR-5a, 1BR-30