

ROLLADEN-SCHNEIDER Flugzeugbau GmbH LBA-Nr. EB - 4	Technische Mitteilung Technical Bulletin Nr. 7008	LS7	Blatt/Page 1/1
			Ausg./Ed. Dez.92

Gegenstand : Winglets

Betroffen : Segelflugzeug LS7, alle Werknummern
Dringlichkeit : wahlweise

Vorgang : Umrüstung auf Winglets und Änderung der Baureihenbezeichnung

Maßnahmen und : Umrüstung entsprechend folgender Zeichnungen:
Material : Trennrippen, Kraftübertragung und Winglets 1BF-94, hinteres
Haubenscharnier 3BR-158a, Änderung der LS7-Wassersäcke (Nur
bei Gesamtmenge 150 Ltr.) entsprechend 1BF-92.
Änderung des Typenschildes von LS7 in LS7-WL sowie Austausch
von Datenschild, Mindestzuladungsschild und Checkliste.
Austausch der Handbücher LS7 gegen LS7-WL sowie Übertrag und
Bescheinigung der bereits durchgeführten TM/LTA.

Gewicht und :
S.P.-Lagen : Müssen neu bestimmt werden, neues Verfahren siehe
Wartungshandbuch Kapitel 2

Hinweise : Bezug der Teile vom Hersteller, Durchführung durch anerkannte
Luftfahrttechnische Betriebe.
Bescheinigung der Durchführung durch einen Prüfer Klasse 3 im
Bordbuch sowie im TM-LTA-Durchführungsbeleg,
Wartungshandbuch Blatt 14-1.
Bescheinigung der Änderung in einem Nachprüfschein
entsprechend LBA-Muster 5, sowie Änderung von
Eintragungsschein und Lufttüchtigkeitszeugnis beim LBA.

LBA-anerkannt :

SUBJECT : Winglets

EFFECTIVITY : Sailplane model LS7, all serial numbers

ACCOMPLISHMENT : Optional

REASON : Modification to winglets and change of model designation.

MATERIAL and : Modification according to the following drawings:
INSTRUCTIONS : Tip connection and winglets 1BF-94, canopy frame rear
temporary hinge 3BR-157a and modification of LS7-water
ballast bags (total volume of 150 Liters only) 1BF-92.
Modification of Type Placard from LS7 to LS7-WL as well as
exchange of Cockpit Checklist, Minimum Cockpit Load Placard
and Data Placard.
Exchange of LS7 manuals against LS7-WL and certification of
already performed TB's and AD's.

WEIGHT AND :
BALANCE : Must be redetermined, new procedure see Maintenance Manual,
chapter 2.

REMARKS : Delivery of parts from manufacturer, accomplishment by
national-authorities approved repair stations.
Inspection and certification of accomplishment by licensed
inspector in logbook and on TB-AD-Accomplishment List,
page 14-1 of Maintenance Manual.

Erstellt: 22.Dez.92 *Heucke*

Geprüft: -7. JAN. 1993 *Ulapha*