

Gegenstand : Zylinderfußdichtung  
Subject : Cylinder-base-gasket

Betroffen/Applicability : Motoren/engine Solo 2625 eingebaut/installed in:  
Typ/type: DG-500, DG-800  
Baureihen/variants DG-800B, DG-808C, DG-500MB

Dringlichkeit : Bei Defekt einer Zylinderfußdichtung.  
Effectivity : In case a cylinder- base -gasket is defective

Vorgang : Die Fa. Solo hat neue verbesserte Zylinderfußdichtungen entwickelt.  
Reason : The Solo company has developed new improved cylinder- base -gaskets.

Massnahmen : 1. Ev. vorhandene Dichtungen, die nicht dem Foto 1 entsprechen, dürfen  
Instructions : nicht verwendet werden.  
2. Prüfen, ob die Zylinderfußschrauben gemäß Foto2 (eingeschnürt)  
ausgeführt sind. Ansonsten auch die Zylinderfußschrauben austauschen.  
1. Don't use cylinder- base -gaskets which you may have on stock other  
than shown in picture 1 below.  
2. Check if the cylinder base studs are of newer necked down design, see  
photo 2. If not, replace the studs by the latest design

Material: DG Bestellnr./DG part no.:  
60500232 Zylinderfußdichtung /cylinder- base -gaskets  
60500180 Dehnschraube Zylinderfuß / necked down cylinder base stud

Bruchsal 2.05.2013

Bearbeiter/Author:

W. Dirks

*Wilhelm Dirks*




Photo 1



Photo 2