DG Flugzeugbau GmbH 76646 Bruchsal	<b>Technical Note</b> No. 413/8	page 1 from 1
Subject	Manual revision	
Effectivity	DG-1000S all ser. no.'s	
Accomplishment	: optional	
Reason	: Manual revision due to latest knowledge	
Instructions	Exchange the following manual pages against new pages is marked with TN 413/8. Flight manual: : 0.1, 0.3, 0.4, 2.7, 3.5, 4.1, 4.17 Maintenance manual: 0.2, 0.4, 0.5, 0.11, 2.6, 6.2, 6.4, 7.1	ssued January 2005
Material	: Manual pages see above.	
Weight and balance	: /	
Remarks	Instructions may be executed by the owner himself. All instructions are to be inspected and entered in the aircr inspector latest with the next annual inspection.	aft logs by a licensed
Bruchsal, date: January 28. 2005	LBA - appr 2 2. FEB. 2005	
Author: Dipl. Ing. Wilhelm Dirks	The German original of this TN has been approved by the and is signed by Mr. Blume.	e LBA under the date of
Wichelmob	The translation into English has been done by best knowledge	
Type certification inspector:	EASA approved on 01. Mar 2005 under Approval No.	2005 - 2034

Dipl. Ing. Swen Lehner

Swen Zelm