Glaser-Dirks Flugzaugbau GmbH

Postfach 4120, PLZ D-76626 Tel. 07257/89-0, Fax 8922 Im Schollengarten 19-20
D-76646 Bruchsal-Untergrombach
LGA aner/cannter Herstellungsbetrieb IB 26 LUA screeks ander Luftform too tiniscreer Cotonic say 279

Technical note Nr. 866-5

page 1 from1

SUBJECT

Retrofit of winglets to the 18m wingtip extensions

EFFECTIVITY

. / .

ACCOMPLISHMENT

DG-600/18M, on choice

REASON

Small winglets (270mm high) may be retrofitted to the 18m wingtip extensions of the DG-600/18.

INSTRUCTIONS

1. Installation of the winglets to the 18m wingtip extensions according to drawing 6F47 and working instruction dated 02. Febr. 1996

2. Exchange of following pages of the flight manual

by the pages issued February 1995:

page 0.1; 0.5; 9.1; 9.4

3. Execute an inspection on the occasion of a

major modification.

Check, if the winglets are installed according to drawing 6F47 and if the flight manual is modified as given in instruction 2). Write an inspection

report with the following note:

"Inspection after retrofit of winglets to the 18m

wingtip extensions according to GLASER-

DIRKS technical note 866-5."

MATERIAL

Flight manual pages 0.1; 0.5; 9.1; 9.4,

issued Feb. 1996 1 set of winglets

1 cutting template according to drawing 6F48

working-instruction dated 02.Feb. 1996

drawing 6F47

WEIGHT AND BALANCE

Influence negligible

REMARKS

Instruction 1 and 3 are to be executed by the manufacturer or by a licensed work-shop and must be inspected by a licensed inspector and are to

be entered into the aircraftlogs.

To execute instruction 1 only the 18m wingtip-

extensions are needed.

Bruchsal, date 02.Feb. 1996

LBA- approved

Author: A.Güntert

Type certification

inspector:

W. Or

W.Dirks

The original of this TN has been approved by the LBA under the date of:.....2.5. März. 1996..... and is signed by Mr. Fendt. The translation has been done by best knowledge and judgement.