Glaser-Dirks Flugzeugbau GmbH Postfach 4120, PLZ D-76825 Tel. 07257/89-0, Fax 89 22 Im Schollengurten 19-20 D-76666 Bruchsal-Untergrombach LBA anertannter Herstellungsbetrich IB 25 LBA anerkannter Luftfahrtechnischer Betrieb IAA 270

Technical note Nr. 370-6

page 1 from1

SUBJECT

Retrofit of winglets to the 18m wingtip extensions

**EFFECTIVITY** 

. 1 .

**ACCOMPLISHMENT** 

DG-600/18, on choice

REASON

Small winglets (270mm high) may be retrofitted to the 18m wingtip extensions of the DG-600/18.

INSTRUCTIONS

1. Installation of the winglets to the 18m wingtip extensions according to drawing 6F47 and working instruction dated 02. Febr. 1996

Exchange of following pages of the flight manual

by the pages issued February 1995:

page 0.1; 0.4; 9.1; 9.4

3. Execute an inspection on the occasion of a

major modification.

Check, if the winglets are installed according to drawing 6F47 and if the flight manual is modified as given in instruction 2). Write an inspection

report with the following note:

" Inspection after retrofit of winglets to the 18m

wingtip extensions according to GLASER-

DIRKS technical note 370-6."

**MATERIAL** 

Flight manual pages 0.1; 0.4; 9.1; 9.4,

issued Feb. 1996 1 set of winglets

1 cutting template according to drawing 6F48

working-instruction dated 02.Feb. 1996

drawing 6F47

WEIGHT AND BALANCE

Influence negligible

REMARKS

Instruction 1 and 3 are to be executed by the manufacturer or by a licensed work-shop and must

be inspected by a licensed inspector and are to

be entered into the aircraftlogs.

To execute instruction 1 only the 18m wingtip

extensions are needed.

Bruchsal, date 02.Feb. 1996

LBA- approved

Author: A.Güntert

The original of this TN has been approved by the LBA under the date of: 2.5. Marz 1996 and is signed by Mr. Fendt. The translation has been done by best knowledge and judgement.

Type certification

10.00

inspector:

W.Dirks