


Rolladen Schneider Flugzeugbau GmbH	Technische Mitteilung Technical Bulletin	No. 4014	Blatt 1 von 1 Page 1 of 1 Ausgabe Edition 24.3.83
--	---	----------	--

Gegenstand	: Wasserballastsystem
Betroffen	: Segelflugzeug, Baureihe LS4
Dringlichkeit	: Wahlweise
Vorgang	: Wasserballastsystem der LS4-a kann eingebaut werden.
Maßnahmen und Material	: Einbau nach Zeichnung 1BF-36
Gewicht und Schwerpunktlagen	: Müssen neu bestimmt werden.
Hinweise	: Die Durchführung der TM 4014 ist vom Prüfer Klasse 3 im Bordbuch zu bescheinigen.

Anerkannt vom  
Luftfahrt-Bundesamt



Subject	: Water ballast system
Effectivity	: Sailplane model LS4
Accomplishment	: Optional
Reason	: The waterballast system of LS4-a can be installed.
Instruction and material	: Installation according to drawing 1BF-36
Weight and balance	: Must be redetermined
Remarks	: Accomplishment must be entered in logbook and signed by inspector.

Approval of translation has been done by best knowledge and judgement. In any case the original text in German language is authoritative.

Anhang : Drawing 1BF-36  
Appendix : Drawing 1BF-33